Weathertzation Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0776/1

Work Order Type: Weatherization

Audit Name: 17017UC-0776

CLIENT INFORMATION

Client ID: 17017UC-0776

Α	GEI	NCY	'INFO	RMA	TION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 *Email Address:*

Agency Contact:Carlisle, RonWork Phone:Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1958 SITE BUILT

Measures

Measure 1	Fix N Fan	lot Operational Kitcher	n Exhaus	t	Componen	ts			Inspected
Comment					Estimated	,		Actual	
# Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
		-	Each	_	Omit Cost	TOtal	Qty	Omit Cost	TOTAL
1 Health and S Items	arety	Equipment	Each	1					
2 Labor		Labor	Hour	1					
Other Detail									
				Measur	e Sub Total:			Sub Total:	
SE SE	JCTS: R SEA :AL/ R	L DUCT IN CLOSET EPAIR LIVING ROOM D AULK INSIDE RETURN					A LL		Inspected
					Estimated	1		Actual	
# Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneou Supplies	IS	Duct Sealing	Each	1					
Other Detail							1		
				Measur	e Sub Total:] ,	Sub Total:	
Field Notes:					L		J	L	

Measure 3 Infi	Itration Redctn			Componen	its			Inspect	
Comment INFILT									
WEATH	HERSTRIPP 2 DOORS U	ISING SILI	CONE			ΓRIP			
			Estimated			Actual			
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Tota	
Miscellaneous Supplies	Infiltration Reduction	Each	1						
Other Detail									
			Measur	e Sub Total:] ,	Sub Total:		
Field Notes:									
Measure 4 DW	H Pipe Insulation			Componer	nts			Inspec	
	H Pipe Insulation			-				Inspect	
Comment				Estimated	<u> </u>		Actual		
Comment Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspect 	
Comment Material / Labor		<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual		
Comment Material / Labor	Description / Comment		-	Estimated	<u> </u>	Qty	Actual		
Comment Material / Labor Insulation	Description / Comment DHW Pipe Insulation		-	Estimated	<u> </u>	Qty	Actual		
Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated	<u> </u>	Qty	Actual		
Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated	<u> </u>	Qty	Actual		
Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated	<u> </u>	Qty	Actual		
* Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated Unit Cost	<u> </u>		Actual		
Measure 4 DW Comment Material / Labor Insulation Labor Other Detail	Description / Comment DHW Pipe Insulation wrap water pipes	Each	1	Estimated	<u> </u>		Actual Unit Cost		

Measure 5 Attic Ins. R-38				1	Inspected			
Comment								
			Estimated	1	Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1356					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
Measure 6 DV	WH Tank Insulation			Componen	ts			Inspecte
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water		Each	4					
Equipment	DHW Tank Insulation	Laon	1					
	DHW Tank Insulation R-10 minimum-use bubble wrap	Lacii	1					
Equipment	R-10 minimum-use	Each	1					
Equipment	R-10 minimum-use bubble wrap							
Equipment 2 Labor	R-10 minimum-use bubble wrap							
Equipment 2 Labor	R-10 minimum-use bubble wrap							
Equipment 2 Labor	R-10 minimum-use bubble wrap		1	e Sub Total:			Sub Total:	
Equipment 2 Labor	R-10 minimum-use bubble wrap		1	e Sub Total:			Sub Total:	
Equipment 2 Labor Other Detail	R-10 minimum-use bubble wrap		1	e Sub Total:			Sub Total:	

Measure 7 CO I	Monitor is Needed			Componen	ts		1	Inspected
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	9-volt CO Monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
] []		
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								
Measure 8 Smo	ke Detector is Needed			Componen	ts		ı	Inspected
Comment				•				
			-	Estimated	<u>'</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	9-volt Smoke Detector	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						,		
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	